Outgoing CO150017

From: Steve Demczak
To: Oakley, Dennis; Suzanne Steab
Date: 8/1/2011 1:49 PM
Subject: Fwd: Attached Image
Attachments: Attached Image



# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

OGM Steve Demczak

JOHN R. BAZA

Division Director

# Representatives Present During the Inspection: Company Guy Davis

# **Inspection Report**

Permit Number:	C0150017
Inspection Type:	PARTIAL
Inspection Date:	Monday, July 18, 2011
Start Date/Time:	7/18/2011 10:00:00 AM
End Date/Time:	7/18/2011 2:00:00 PM
Last Inspection:	Tuesday, June 14, 2011

Inspector: Steve Demczak,

Weather: Sunny, 80's

InspectionID Report Number: 2806

**Types of Operations** 

Accepted by: jhelfric 7/28/2011

Permitee: ENERGY WEST MINING CO Operator: ENERGY WEST MINING CO Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

#### **Current Acreages**

Total Permitted	133.90
Total Disturbed	40.90
Phase i	136.58
Phase II	95.70
Phase III	95.70

#### Mineral Ownership

Y	Federal	<b>✓</b> Underground
1	State	Surface
	County	Loadout
✓.	Fee	Processing
	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violation were issued.

Inspector's Signature:

Inspector ID Number: 39

Date

Wednesday,

OIL GAS & MINING

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, July 18, 2011

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
    b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	rearra	; mm		
2.	Signs and Markers	Z	:"":	Y	
3.	Topsoil	<b>V</b>		<b>y</b>	,,,,,
4.a	Hydrologic Balance: Diversions	V	, 100 mg	Y	( )
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		<u> </u>		
4.¢	Hydrologic Balance: Other Sediment Control Measures	✓.		<b>V</b>	
4.d	Hydrologic Balance: Water Monitoring	:]		: 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		7		
6.	Disposal of Excess Spoil, Fills, Benches			in the second	American Page
7.	Coal Mine Waste, Refuse Piles, Impoundments		(1)	2 * **** 1	( <u>)</u>
8.	Noncoal Waste	<b>V</b>		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues			:	
10.	Slides and Other Damage	~		~	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	~		<b>V</b>	
13.	Revegetation		<u></u>		
14.	Subsidence Control				
15.	Cessation of Operations			g	[::]
16.8	Roads: Construction, Maintenance, Surfacing				1
16.b	Roads: Drainage Controls		;******* 		
17.	Other Transportation Facilities				gh 1411000
18.	Support Facilities, Utility Installations	<b>y</b>	3	¥	
19.	AVS Check			[	
20.	Air Quality Permit				
21.	Bonding and Insurance			1.1	
22.	Other			V*****	

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, July 18, 2011

Page 3 of 3

#### 2. Signs and Markers

The identification signs is located on the trail to the mine site.

## 3. Topsoil

All topsoil was used in reclamation.

## 4.a Hydrologic Balance: Diversions

Diversions were spot-checked and would function in a storm event. There were no signs of water erosion to the diversion.

## 4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to control sediment control.

## 8. Noncoal Waste

The area was clear of non-coal waste material.

## 10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

#### 12. Backfilling And Grading

The site is backfilled and graded to AOC standards in my opinion.

## 18. Support Facilities, Utility Installations

There are no facilities at this site.